


H41H lift check valve



1,6 МПа

выбирать Расследование Ду(мм)

Размер и размер соединения (мм)

Исходное значение ЧАС

выбирать			Размер и размер соединения (мм)						Исходное значение	
Расследование	Ду(мм)	мм	л	Д	Д1	Д2	Д6	Б	Z-φd	ЧАС
15	130	95	65	45	-	14	4-14	90/77		
20	150	105	75	55	-	14	4-14	95/77		
25	160	115	85	65	-	14	4-14	100/80		
32	180	135	100	78	-	16	4-18	105/85		
40	200	145	110	85	-	16	4-18	110/95		
50	230	160	125	100	-	16	4-18	115/105		
65	290	180	145	120	-	18	4-18	140/120		
80	310	195	160	135	-	20	8-18	170/130		
100	350	215	180	155	-	20	8-18	200/140		
125	400	245	210	185	-	22	8-18	230/155		
150	480	280	240	210	-	24	8-23	255/180		
200	600	335	295	265	-	26	12-23	285/215		
250	650	405	355	320	-	30	12-25	290/260		
300	750	460	410	375	-	30	12-25	300/315		
400	1100	580	525	485	-	36	16-30	-		
500	1250	705	650	608	-	44	20-34	-		